



Asbestos Sample Results (Method EPA 600/R-93/116)			
Sample ID	Location	Description	Result
AB-004	Admin Building Northeast Entrance	Tar Shingle Roofing and Silver Sealant	ND
AB-005	Admin Building Southwest Chimney	Tar Shingle Roofing and Silver Sealant	ND
Lead Sample Results (Method SW 846 3050B/7000B)			
Sample ID	Description	Location	Result
AB-PB-03	Green paint on concrete (2" by .5")	Admin Building Chimney	0.1

LEGEND

- 01234 ASBESTOS SAMPLE LOCATIONS
NEGATIVE (<1% ASBESTOS)
 - 01234 ASBESTOS SAMPLE LOCATIONS
POSITIVE (≥ 1% ASBESTOS)
 - 01234 LEAD BASED PAINT SAMPLE
(<1 mg/cm²)(HUD)
 - 01234 LEAD BASED PAINT SAMPLE
(>1 mg/cm²)(HUD)
- SEE ASBESTOS TABULATION RESULTS
FOR CONCENTRATION FOR ASBESTOS
SAMPLE NUMBER
- SEE LEAD BASED PAINT TABULATION
RESULTS FOR CONCENTRATION FOR
LEAD SAMPLE NUMBER

PALMER CORRECTIONAL CENTER - DEFERRED MAINTENANCE

(DOT&PF PROJ. NO. RSA2013000)
DEPARTMENT OF TRANSPORTATION AND PUBLIC FACILITIES
2200 E AST 42nd AVENUE, ANCHORAGE, ALASKA 99508

65% REVIEW DOCUMENTS

CONSULTANT:

NORTECH

SUSTAINABLE ENVIRONMENT
ENERGY, HEALTH & SAFETY

Fairbanks: 2400 College Road
907.452.5688

Anchorage: 3105 Lakeshore Drive
Juneau: 5438 Shauna Drive
Corporate No.: AECC682

PROJECT NO:	20-116	
DATE:	04/08/2020	
DRAWN BY:	AES	
CHECKED BY:	PLB	
Symbol	Description	Date

ADMINISTRATION

ROOF ASBESTOS & LEAD
SAMPLE LOCATIONS & RESULTS

H201

ARCHITECT: BETTISWORTH NORTH

2600 DENALI STREET SUITE 700 ANCHORAGE, ALASKA 99503 (907) 561-5780
212 FRONT STREET FAIRBANKS, ALASKA 99701 (907) 456-5780
CORPORATE No. AECC299 WWW.BETTISWORTHNORTH.COM