STATE OF ALASKA ITB NUMBER 2524S002 AMENDMENT NUMBER ONE

RETURN THIS AMENDMENT TO THE ISSUING OFFICE AT:



Department of Transportation & Public Facilities Division of Facility Services 3132 Channel Drive, Suite 350 Juneau, AK 99811-2500

THIS IS NOT AN ORDER

DATE AMENDMENT ISSUED: April 25, 2023

FIRE SPRINKLER INSPECTION, TESTING, & REPAIR SERVICES FOR JUNEAU FACILITIES

ITB OPENING DATE AND TIME: May 11, 2023, at 2:00 PM

The State received the following questions concerning the system in the Alaska Office Building

- 1. What class the standpipes are at the Alaska Office Building? 1
- 2. Are they wet or dry and do you know if they are combined? Wet, no.
- 3. Do they have hoses on them? No, the only service are the FD services in stairwells. No hoses, just the hookups.
- 4. For the dry system trip, are you wanting a full system trip? Partial flow unless for certain dry pipe valve models a partial flow test may not provide a high enough rate of flow to latch the clapper in the open position. If the manufacturer's instructions indicate that this is the case for your model, it's important to test that the latching equipment is operative when resetting the valve.

This is a mandatory return Amendment. Your bid may be considered non-responsive if this signed amendment is not received [in addition to your bid packet] by the date and time proposals are due.

Matthew L Pegues Procurement Specialist IV PHONE: 907-465-5889 matthew.pegues@alaska.gov

NAME OF COMPANY

SIGNATURE

DATE