

Attachment #3

BAAF 47437 Photos

Large Bay Photos



Large Bay HVAC Photos



Small Bay Photos



← Small Bay HVAC Photos



Small Office (Connected To Large Bay) Photos



Damper that is not working properly.




← Small Office Lighting

Hallway Lighting



Hallway/Large Office Flooring



Proposed Location For Drinking Fountain With Bottle Filler (Bid Alt #1). This Is The Space Between Male & Female Restroom Doors. Actual Location Will Be Ironed Out With Successful Bidder At The Pre-Construction Meeting.


Example of Ceiling Tiles In Hallway



Large Office Lighting







Large Office



Large Office Ceiling Example



Large Office/Hallway Walls Example Photos




Women's Restroom Photos




Men's Restroom Photos



Men's Restroom Lighting Example Photos



Men's Shower Photos, Note 3 Fixtures With 3 Shower Heads (No Temperature Control Only On Or Off)



Mechanical Room HVAC Photos

