



1 M501 DIAGRAM – WATER SERVICE ENTRY AND FIRE PROTECTION

SCALE: NONE



2 M501 DIAGRAM – NATURAL GAS METER PIPING REVISIONS

SCALE: NONE



NOTES:

1. DUCT/PIPE SHALL NOT CONTACT WALL.
2. CAULKING SHALL FORM AIR-TIGHT SEAL AROUND DUCT/PIPE.
3. TERMINATE AND SEAL DUCT/PIPE INSULATION ON BOTH SIDES OF WALL PENETRATION.

3 M501 DETAIL – DUCT/PIPE WALL PENETRATION

SCALE: NONE



4 M501 DETAIL – EXHAUST FAN (EF-1) MOUNTING

SCALE: NONE



5 M501 DETAIL – RELIEF LOUVER

SCALE: NONE

RIM ARCHITECTS
ALASKA | HAWAII GUAM CALIFORNIA
645 'G' STREET, SUITE 400
ANCHORAGE, ALASKA 99501
Phone: 907.258.7777
Fax: 907.279.8195
www.rimarchitects.com

STATE OF ALASKA 49TH
Bart A. Semmler
04/07/2017
ME-13385
REGISTERED PROFESSIONAL ENGINEER
© 17605

AMC ENGINEERS
www.amc-engineers.com
Adams, Morgenthaler & Co., Inc.
CoA No. C0342 - 907.257.9100
701 E. Tudor Rd. Suite 250
Anchorage, AK 99503

PROJECT TITLE: UAA ANSEP ULA RENOVATION
ADDRESS: UNIVERSITY LAKE BUILDING - BUILDING AO 107
OWNER: UNIVERSITY OF ALASKA ANCHORAGE
SHEET TITLE: DETAILS AND DIAGRAMS

NO	DESCRIPTION	DATE

DATE : 2017.04.07
PROJECT NO : 17-0103
DRAWN BY : BAS
CHECKED BY : MDL
COPYRIGHT : 2015 RIM ARCHITECTS

DWG NO: M501

FILE NAME: X:\17605 ANSEP\Dwgs\Mdwg\Sheet Files\17605 - M501.dwg
PLOTTED: BAS 4/7/2017 4:18 PM