Byron Mallott Lieutenant Governor State Capitol Juneau, Alaska 99811 907.465.3520 465.5400 Fax WWW.LTGOV.ALASKA.GOV



530 West 7th Ave, Suite 1700 Anchorage, Alaska 99501 907.269.7460 269.0263 LT.GOVERNOR@ALASKA.GOV

OFFICE OF THE LIEUTENANT GOVERNOR ALASKA

MEMORANDUM

TO:

Jun Maiquis, AAC Contact

Department of Commerce, Community and Economic Development

FROM:

Scott Meriwether

Special Assistant

907.465.4081

DATE:

July 20, 2015

RE:

Filed Permanent Regulations: Board of Marine Pilots

Regulations re: pilot stations and pickup points (12 AAC 56.120(a))

Attorney General File:

JU2015200311

Regulation Filed:

July 19, 2015

Effective Date:

August 18, 2015

Print:

215, October 2015

cc with enclosures:

Linda Miller, Department of Law

Genevieve Wojtusik, Administrative Regulation Review Committee

Judy Herndon, LexisNexis

ORDER CERTIFYING THE CHANGES TO REGULATIONS OF THE BOARD OF MARINE PILOTS

The attached two pages of regulations, dealing with pilot stations or pickup points, are hereby certified to be a correct copy of the regulation changes that the Board of Marine Pilots adopted at its May 28, 2015 teleconference meeting, under the authority of AS 08.62.040 and after compliance with the Administrative Procedure Act (AS 44.62), specifically including notice under AS 44.62.190 and 44.62.200 and opportunity for public comment under AS 44.62.210.

This action is not expected to require an increased appropriation.

Although no public comments were received, the Board of Marine Pilots paid special attention to the cost to private persons of the regulatory action being taken.

The regulation changes described in this order take effect on the 30th day after they have been filed by the lieutenant governor, as provided in AS 44.62.180.

DATE:

Juneau, Alaska

Chris Hladick, Chairman Board of Marine Pilots

FILING CERTIFICATION

I, Byron Mallott, Lieutenant Governor for the State of Alaska, certify that on ________, 2015 at 850 g.m., I filed the attached regulations according to the provisions of AS 44.62.040 – 44.62.120.

Byron Mallott, Lieutenant Governor

Effective: August 18, 2015.

Register: 215 October 2015.

Chapter 56. Board of Marine Pilots.

12 AAC 56.120(a)(37) is amended to read:


240° [180°] true the

(37) Nushagak Bay $-\frac{7.5}{100}$ [0.6] miles $\frac{240T}{1000}$ [180° TRUE] from south tip of

Etolin Point [NUSHAGAK BAY ENTRANCE LIGHTED BELL BUOY]; approximate position 58° 33' north latitude, 158° 24' west longitude;

12 AAC 56.120(a)(40) is amended to read:

(40) Kuskokwim Bay [RIVER] Region



(A) Kuskokwim Bay [RIVER] - 17.4 miles 320T from Cape

Newenham, approximate position 58° 52' [59° 42'] north latitude, 162° 32' [19'] west longitude;

- (B) Goodnews Bay 7.5 miles 228° true from Platinum; approximate position 58° 55' north latitude, 162° 00' west longitude;
- 12 AAC 56.120(a) is amended by adding new paragraphs to read:
 - (51) Barrow 3.0 miles 320F from the town of Barrow, approximate position

71° 20' north latitude, 156° 53' west longitude;

OIS° true

(52) Kotzebue Sound – 11.0 miles **%15T** from Cape Espenberg Light;

approximate position 66° 44' north latitude, 163° 29' west longitude;

figures are zeroes (53) Port Clarence - 2.1 miles 000F from Point Spencer Light; approximate

position 65° 19' north latitude, 166° 51' west longitude;

(54) Nome – 2.6 miles 199T from the Nome north jetty breakwall; approximate

Register 2/5, October 2015 PROFESSIONAL REGULATIONS

position 64° 27' north latitude, 165° 28' west longitude.



(Eff. 3/30/86, Register 97; am 8/29/87, Register 103; am 4/12/89, Register 110; am 6/17/90, Register 114; em am 7/2/90 - 10/29/90, Register 115; am 8/17/91, Register 119; am 11/7/93, Register 128; am 11/10/93, Register 128; am 5/29/96, Register 138; am 6/17/96, Register 138; am 1/23/99, Register 149; am 3/21/99, Register 149; am 5/31/2000, Register 154; am 6/24/2012, Register 202; am 8/18/2015, Register 215)

Authority: AS 08.62.040