



CONCRETE RESURFACING NOTES:

- 1. ENSURE THAT CONCRETE HAS BEEN PREPARED IN ACCORDANCE WITH THE CONCRETE RESURFACING PREPARATION NOTES ON C3, MANUFACTURERS RECOMMENDATIONS AND IS SATURATED SURFACE-DRY.
- CONCRETE RESURFACING MATERIAL SHALL BE A ONE-COMPONENT, POLYMER MODIFIED, CEMENTITIOUS MATERIAL.
- 3. CONTRACTOR SHALL SUBMIT CONCRETE RESURFACING MATERIALS, ADMIXTURES AND SEALERS FOR APPROVAL. ALL COMPONENTS SHALL BE FROM ONE MANUFACTURER TO ENSURE COMPATIBILITY.
- PRIME CONCRETE SURFACE WITH A WATER BASED ONE-COMPONENT LATEX ADDITIVE IN ACCORDANCE WITH MANUFACTURERS RECOMMENDATIONS.
- 5. MIX AND APPLY THE PRODUCT PER MANUFACTURERS RECOMMENDATIONS ENSURING THAT ALL EXPANSION AND CONTROL JOINTS ARE HONORED.
- 6. PROTECT AND CURE THE CONCRETE SURFACE PER MANUFACTURERS RECOMMENDATIONS.
- 7. SEAL THE SURFACE WITH A FILM-FORMING, WATER BASED SEALER AFTER SIDEWALKS HAVE CURED.

SITE PLAN NOTES:

- 1. ALL NEW WORK SHALL MATCH EXISTING GROUND ELEVATIONS AND GRADES UNLESS OTHER WISE NOTED.
- SIDEWALK SHALL BE IN ACCORDANCE WITH MASS SECTION 30.03 PORTLAND CEMENT CONCRETE SIDEWALK, CLASS A-3, 6 INCHES THICK AND BROOM FINISHED WITH 6x6-W2.9/W2.9 WELDED WIRE MESH PLACED MID DEPTH.
- 3. INSTALL EXISTING CANOPY BRACKETS IN SIDEWALK.
- 4. MAINTAIN ACCESS TO ALL COTTAGES, SCHOOL AND CAFETERIA AT ALL TIMES.
- 5. MAINTAIN ELECTRICAL POWER TO ALL COTTAGES, SCHOOL AND CAFETERIA AT ALL TIMES.
- 6. SIDEWALK SHALL BE CROWNED IN THE MIDDLE WITH 1% SLOPES TO EACH SIDE.
- 7. ALL NEW TO EXISTING SIDEWALK CONNECTIONS TO BE DOWELED PER DETAIL F/C7.



9101 Vanguard Drive
Anchorage, Alaska 99507
Som. email@rmconsult.com
522.1707 • fax: 907.522.3403
CERT OF AUTH. AECOT11



STATE OF ALASKA
DEPT. OF HEALTH & SOCIAL SERVICI
MCLAUGHLIN YOUTH CENTER PARKING LOT RENOVATIONS
ANCHORAGE, ALASKA

No. Description Date

ADDENDUM 1 081718

Disambr. Description

CB NK

Signature

August 3, 2018

Pase:
Bid Documents

Bid Documents
Project No:
R&M 2649.01

SITE PLAN SIDEWALK

QUEET N

C6