

VICINITY MAP

1" = 1 MILE

LEGEND

- GPS CONTROL POINT MONUMENT SET THIS SURVEY (#5 REBAR WITH PLASTIC CAP)

Entrance Island

U.S. Forest Service

*Hobart Bay
T51S R75E
Section 30
C.R.M.*

AKSPC Z1 N: 2037682.2175
AKSPC Z1 E: 2730079.9443
LATITUDE: 57°24'46.0928"
LONGITUDE: -133°26'34.0319"

BARGE
(ROTTEN)

MEANDER LINE
S53°03'12"E
371.77'


S20°25'03"W
281.88'

S81°07'56"W
119.03'

AKSPC Z1 N: 2037477.1054
AKSPC Z1 E: 2730494.6680
LATITUDE: 57°24'44.0582"
LONGITUDE: -133°26'26.4716"

S69°11'44"E
194.63'

WOOD REFUGE FLOAT
Proposed ATSLMA Boundary Lines
Used by Recreational Boaters and
Commercial Fishermen



AREA = 1.15 acres

S20°25'03"W
196.01'

BUILDING

FLOAT POSITION		
N 57°24'45.3"	W 133°26'26.6"	W. END
N 57°24'45.0"	W 133°26'25.0"	E. END

GENERAL NOTES

1. No Alaska Tidelands Survey or ADL identification number on record for this facility.
2. *** GPS positions for this location are degraded due to poor satellite visibility and short occupation times. Use coordinates with caution.
3. *** Due to the lack of recovered monumentation, the refuge float and other structures are shown in relation to the meander line of the shore.

Fieldwork conducted June 11, 2008 by DOT/PF Survey Crew Johnson, Cottrell.

Entrance Island Float

Juneau Recording District

SURVEYOR: State of Alaska D.O.T./P.F. Southeast Region

OWNERS:
STATE OF ALASKA
DEPT. OF NATURAL
RESOURCES

SCALE: 1" = 50'
DATE: 9/2013

SHEET 1 OF 1