

Alaska Department of Military and Veterans Affairs
Division of Administrative Services

Invitation for Quotes # 09-001-26

AMYA Warehouse Roof and Siding Repairs

Addendum 2

Date of Issue: 9/11/2025

Addendum 2 serves to provide site photos in response to a request from an interested offeror. This Addendum 2 is hereby made part of the IFQ and is a total of 9 pages.

Issued by:


Jannah Cayetano/Procurement Specialist 3

Email: MvaDasProcurement@alaska.gov

Site Photos



Roof and Siding



Inside Ceiling



Main personnel door. Significant water leaks in this area.





Significant water leaks in this area.



Snow accumulates on the door roofs and leaks into the building where the ceiling and walls meet.





There is a large gap between the asphalt and the building, which allows water to enter underneath the walls.





Water enters the building from underneath the garage door.

End of Addendum 2