



Beluga Slough Outlet Maintenance Project Site Natural Features



The 2019 contour lines indicate where the engineered outflow established to mitigate storm berm buildup. The channel diverts flow eastward and is eventually blocked off.

Data Source
 Contours: 2019 LiDAR, AKDGGs
 Mean High Tide: NOAA CUSP
 Aerial: MAXAR, Collection Date-
 9/4/2023